



EASA Safety Information Notice

No.: 2008-16

Issued: 28 February 2008

Subject: Auxiliary Power Units (APU's) and component parts that have been improperly returned to service

Ref. Publication: FAA Unapproved Parts Notification (UPN) No. S2007-00727004.

Introduction: The Federal Aviation Administration (FAA) has published the referenced UPN (attached as pages 2 through 6 of this notice) as a result of an investigation that revealed that auxiliary power units and component parts have been improperly returned to service with fraudulently produced documents similar to the FAA Form 8130-3, Airworthiness Approval Tag, representing the items as aircraft parts and certifying they were maintained in accordance with 14 Code of Federal Regulations (14 CFR) part 43.

Applicability: Any aircraft and/or engines, as applicable, which have auxiliary power units and component parts installed, as identified in the attached FAA UPN. The FAA has been unable to determine the affected aircraft and engines (type designs).

Recommendation: This Safety Information Notice is for information only.

Contact: For further information contact the Airworthiness Directives, Safety Management and Research Section, Certification Directorate, EASA.
E-mail: ADs@easa.europa.eu .